



JON M. HUNTSMAN, JR.  
Governor

GARY R. HERBERT  
Lieutenant Governor

# State of Utah

## DEPARTMENT OF NATURAL RESOURCES

### Division of Oil, Gas & Mining

MICHAEL R. STYLER  
Executive Director

JOHN R. BAZA  
Division Director

### Inspection Report

#### Minerals Regulatory Program

Report Date: September 25, 2006

Supervisor ADZ

**Mine Name:** Black Ridge  
**Operator Name:** Thirstystone Resources, Inc.  
Pete Raymond  
860 East 19<sup>th</sup> Street  
Tucson, Arizona 85719-6615

**Permit number:** S/053/027  
**Date:** September 12, 2006  
**Time:** 4:45 PM

**Inspector(s):** Doug Jensen  
**Other Participants:** None  
**Mine Status:** Inactive

**Weather:** Clear, hot

#### Elements of Inspection

1. Permits, Revisions, Transfer, Bonds
2. Public Safety (shafts, adits, trash, signs, highwalls)
3. Protection of Drainages / Erosion Control
4. Deleterious Material
5. Roads (maintenance, surfacing, dust control, safety)
6. Concurrent Reclamation
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts, drill holes)
8. Water Impoundments
9. Soils
10. Revegetation
11. Air Quality
12. Other

Evaluated	Comment	Enforcement
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

#### Purpose of Inspection:

Inspected the site to check for recent activity.

#### Directions to Site:

See previous inspection report.

#### Inspection Summary:

The site remains unchanged; this site has been inactive for four or five years. The road into the site is still washed out, no effort has been made to fix the road.

#### Conclusions and Recommendations:

Because this site has been inactive for at least four years, the operator should contemplate the reclamation.

**Inspector's Signature**

Doug Jensen

**Date:**

9/25/06

dj:pb

cc: Pete Raymond  
Russ Schreiner, BLM, St George FO UTU 68868

O:\M053-Washington\S0530027-BlackRidge\inspections\09122006insp-blank.doc





ROAD INTO SITE, QUARRY IN THE DISTANCE